


Date: Wednesday, 04/06/2008 8:34:12 AM
User: Linda Lacelle

Process Sheet

Customer :	CC-DAR01 Dart Aerospace Ltd.	Drawing Name :	D2521
Job Number :	39687		
Estimate Number :	10804		
P.O. Number :		Part Number :	SCRAP30
This Issue :	04/06/2008	S.O. No. :	
Prsht Rev. :	NC	Drawing Number :	SCRAP- CHG002
First Issue :	/ /	Project Number :	
Previous Run :	00015	Drawing Revision :	
Written By :		Material :	
Checked & Approved By :		Due Date :	11/06/2008
Comment :		Qty:	1
		Um:	Each

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

PULL FROM STOCK:

1 X D2521 B25763

SB 08/06/04

①

2.0	D2521	Bearpaw 205
-----	-------	-------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)
Bearpaw 205

SB 08/06/04

②

3.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
-----	-------------	-------------------------------



Comment: SMALL & MEDIUM FAB RESOURCE 1

SCRAP / DESTROY
TOO OLD CHG #

→ 08/06/04 ① Jim

4.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



Comment: FINAL INSPECTION/W/O RELEASE

08/07/04

Job Completion



W 08-06-30